

## ASSEMBLY INSTRUCTIONS:

Product Code : CL410

Product Name: CL410 Chair

rapidline

### TIME REQUIRED:

20 minutes

### TOOLS REQUIRED:

Screwdriver, Electric Drill, Pencil, Measuring tape/Ruler

\*Tools are not included.

### SKILL REQUIRED:

Easy  Hard

The Assembly Skill Rating is a 5-point system that shows the degree of effort needed in assembling a specific product. With 1 being easy for the average person and 5 requiring an expert. For most products, two persons are recommended.

#### NOTE

- As this is a commercial product, some intermediate skills may be required.
  - No pre-drill holes or markings are provided on our table or desk tops.
  - Please check you have all hardware before assembling.
- If you are missing any hardware, please contact your Rapidline reseller. Please ensure you have the name of the item, required hardware part and quantity.
  - Please retain your receipt as proof of purchase to validate your warranty.
- Assemble on a clean, flat, smooth surface such as a rug or carpet to avoid parts from being scratched.
- Remove all wrapping materials, including staples and packing straps before you start to assemble
  - Keep all hardware parts out of reach of children.







#### CAUTION

- Heavy product. Do not attempt to lift or move without help
- Do not tighten screws and bolts until completely assembled.
- Do not use this product unless all bolts and screws are firmly secured and tightened.

#### WARNING

- If parts are missing, broken, damaged or worn stop using the product until all repairs are made.
- Failure to follow these warnings could result in serious injury.

# CL410

|                                                                                    |                                                                                                                                          |                                                                                          |                                                                                                |                                                                                     |                                                                                                                                  |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|
| (1)                                                                                | (2)                                                                                                                                      | (3)                                                                                      | (4)                                                                                            | (5)                                                                                 | (6)                                                                                                                              |
|   | <br>X2                                                  | <br>X5 |             |  | <br>X4 6X20 X4 8x50<br>X4 X4 6X30<br>6M 5M X4 |
| A                                                                                  | B                                                                                                                                        |                                                                                          | C                                                                                              |                                                                                     |                                              |
|  | <br>6X20 6X20 6X20 6X20<br>STEP 1<br>STEP 2<br>X4 6X30 |                                                                                          | <br>X2 8x50 |                                                                                     |                                                                                                                                  |